Approved For Release 2000/09/01 CIA-RDP81Be0878R001400030100-8

SAPC- 14594 Copy 2 of 5

12 April 1957


Dear Bob:


During Dan's visit a question was raised as to location of certain equipment in order to determine patch cable requirements.

It is our understanding that a set of patch cables will be required for each type of rack (Systems 1 and 3) at each location. On the basis of this criteria and the best available current information 76 sets of cable will be required for these systems. The contract presently is funded for 82 sets at \$246.95 each.

Yours very truly,

George





Approved For Release 2000/09/01 CIA-RDP81B00878R001400030100-8